

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

DATE: 5/13/85

SUBJECT: Potential Hazardous Waste Site  
 FROM: Keith Bradley, FIT RPO  
 Hazardous Waste Section (6ES-SH)  
 TO: Martha McKee, Chief  
 Compliance Section (6AW-SC)

OKD981 052566

Site Name: King Fisher County Feed Yard #2  
 Location: Okarche OK  
 Hazsit No.: OK 5-134  
 TDD No.: R6-850 2-12

RECEIVED  
 EPA REGION VI  
 1985 MAY 15 AM 9:49  
 SUPERFUND BRANCH

A. Deliverables:

- |   |              |
|---|--------------|
| 1. Preliminary Assessment (Form 2070-2) | attached ( ) |
| 2. Site Inspection Report (Form 2070-3) | attached ( ) |
| 3. Sampling Inspection Report           | attached ( ) |
| 4. Other: _____                         | attached ( ) |

B. Were drinking water wells sampled? Yes ( ) No (X)

C. Analytical Data:

- |                         |              |
|-------------------------|--------------|
| 1. None collected       | ( )          |
| 2. Field data           | ( )          |
| 3. Contract lab results | attached ( ) |
| 4. Houston lab results  | attached ( ) |

D. Comments:

FIT recommends that no further action be taken at this site since no evidence of surface run off or hazards to health and environment were observed.

9417667



SUPERFUND FILE

cc:(circle) Cabra 6W-MS  
 Gazda 6ES-E  
 Taylor 6AW-HE

JUL 13 1992

REORGANIZED